



SHANGHAI RESEARCH

INSTITUTE OF BUILDING SCIENCES CO.,LTD.

资质证书编号: A231023592

合作设计单位 CO-OPERATED WITH

单位出图专用章 AUTHORIZED COMPANY SEAL FOR ISSUE

注册建筑师执业章 REGISTERED ARCHITECT'S PRACTICE SEAL

注册工程师执业章 REGISTERED ENGINEER'S PRACTICE SEAL

审 定 APPROVED BY	金艳萍	金艳萍
项目经理 PROJECT MANAGER	吉峰	吉峰
项目负责人 PROJECT DIRECTOR	吕申婴	吕申婴
审 核 REVIEWED BY	吕申婴	吕申婴
校 对 CHECKED BY	陈国园	陈国园
专业负责人 DISCIPLINE RESPONSIBLE	吕申婴	吕申婴
设 计 DESIGNED BY	姜艳隽	姜艳隽
制 图 DRAWN BY	姜艳隽	姜艳隽
会签 CONFIRM BY	建筑 ARCHITECTURE 电气 ELECTRICITY 给排水 PLUMBING	结构 STRUCTURE 暖通 HVAC

建设单位 CLIENT

上海市复兴实验中学

项目名称 PROJECT	2025年虹口区学校加装无障碍电梯 (上海市复兴实验中学)
-----------------	----------------------------------

子 项	
SUB-PROJECT	


图 名 DRAWING TITLE	剖面, 立面图
-------------------------	---------

设计号 JOB NO.	HT0062025001171
----------------	-----------------

专 业 DISCIPLINE	建筑	阶 段 STATUS	施工图
-------------------	----	---------------	-----


图号 DRAWING NO.	07	日期 DATE	2025.07
-------------------	----	------------	---------

• 安部



1-1剖面图 1:100

- 注: 1.井道尺寸均按电梯安装方提供参数要求设计,施工前必须经电梯安装方再次确认方可实施。
2.电梯安装所需预埋件由电梯安装方提供,并按要求安装。
3.每层电梯门套采用100号(外凸20)拉丝不锈钢。
4.候梯厅墙饰均按主体建筑项目要求施工。
5.因施工过程中造成主体建筑内饰层的损坏均按原样修复。



东立面图 1:100

- 注:1.铝板颜色按主体建筑项目外立面协调考虑。
2.铝板分割由安装方按图示深化。
3.因施工过程中造成主体建筑外立面的损坏均按原样修复。